





3D METAL MODEL KITS

METAL SHEETS




In order to avoid possible injury from sharp edges, please carefully




ICX022

USS Theodore Roosevelt Carrier



TO CREATE THE BEST CONNECTIONS



Legends:

- Engraved side
- Non-engraved side
- Attention point
- Insert tab and bend 90 degrees
- Insert tab and twist 90 degrees



Recommended tools:

- Wire cutters: helpful for taking parts from the metal sheets.
- Tweezers or needle nose pliers: helpful for folding parts, bending and twisting tabs.


Assembly tip:

If needed, slightly twist tabs to hold parts together then untwist and bend them down for a nice finish


ASSEMBLY STEPS




Step 3




Step 4




Step 5




Step 6



Step 7




Step 8




Step 9




Step 10




Step 11




Step 12




Step 13




Step 14




Step 15




Step 16



Step 17



Step 18



Step 19

